



Solvent thinner

| | |
|------------------------|--------------------------------|
| Recommended use | Thinner for alkyd based paints |
|------------------------|--------------------------------|

Physical Properties

| | |
|-------------------------|--------------------------|
| Finish and Color | Clear |
| Specific gravity | Approx. 0.87 |
| Solids by volume | 0% |
| Flash point | 25°C / 77°F (Closed cup) |

Application details

| | |
|----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Surface preparation | <p>PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Avoid contact with eyes, skin, and clothing. Keep out of the reach of children. Protect against physical damage. Use with adequate ventilation. Worker must wear air-purifying respirator, safety goggle, protective clothing and glove to prevent contact with this material. Keep container tightly closed. Flammable liquid and vapor may cause flash fire. Keep away from all ignition sources such as heat, open flame, spark. Store away from incompatible substances(oxidizing materials, acid or base). Keep container cool. Avoid prolonged breathing of vapors and mists. Use spark resistant tools. Approved air supplied type respirator should be used in confined spaces, especially such as inside of tank. Wash thoroughly after handling. When electrostatic coating is required, please wear electric resistant shoes or protective equipment.</p> |
|----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

Storage and package

| | |
|---------------------|-----------------------------------------|
| Packing Unit | Container (4 Litre, 18 Litre, 20 Litre) |
|---------------------|-----------------------------------------|

Remarks

| | |
|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Handling Precautions | <p>FIRST AID MEASURES:</p> <p>INHALATION: Remove from exposure area to fresh air immediately. Perform artificial respiration if necessary. Keep person warm and at rest. Get medical attention immediately.</p> <p>EYES: Wash eyes immediately with large amounts of water occasionally lifting upper and lower lids, until no evidence of chemical remains(at least 15~20 minutes). Get medical attention immediately.</p> <p>SKIN: Remove contaminated clothing and shoes immediately. Launder before re-use. Wash affected area thoroughly with soap and water until no evidence of chemical remains(at least 15~20 minutes). Get medical attention immediately.</p> <p>SWALLOW : Extreme care must be used to prevent aspiration. Do not induce vomiting. Get medical attention immediately</p> |
| 1'st issue | 2014-08-01 |
| Revision | 2017-02-09 |



able to guarantee without the confirmation of the purpose of using the product from us in writing. We reserve the right to change the data without notice and you should check that this data sheet is current prior to using the product.

